


# Sensor value report

Report date: 15.1.2025 16.00.00 - 16.1.2025 16.00.00

Asset: VDW - Repair Centre GPRS Gateway TGG Tel: +316 57105258



- last measurement less than 10 measurement intervals before
- last measurement more than 10 measurement intervals before
- no data for last measurement

Node	Sensor	Unit	Min value	Max value	Avg value	Latest measurement	Latest value	State
B02 - Sensor 1	Ext Temperature 1	°C	2.7	13.1	4.346	27.1.2025 12.01.59	13.1	●